POWER SUPPLY P.C. 80-904

16.5V
9 V.
C. TAP
9 V.
16.5V.
13
14
17
16
18
(2) IN4004
(2) IN5624
6000 MF. 35 V.
0.1 MF. 50V
0.1 MF. 50V.
10MF. 25V.
BZX61C16
78M12UC LM340-12
220 Ω 1W.
9 +16V. OPTION
2 +12V.
3 +12V.
10 MF. 25V.
+ SENSE STRAP
23 +SENSE
21 +5V.
22 +5V.
2N3055 *1
0.18Ω 5W
0.1MF. 50V
68Ω 1/2W
4.7Ω 1/2W
2N2905
27Ω
20000 MF. 16V.
1K Ω 1W.
1K Ω
1.8K Ω
IN4004
470MF. 16V.
100Ω POT
910Ω
2.2KΩ
0.1MF. 50V.
2N4125
10K Ω
6 RESET
10K Ω
2N4123
15Ω
5.6K Ω
10Ω
24 -SENSE
20 COM
5 TILT
1 -5V
12 V. IND.
15 V. LED
4 LED & LAMP RETURN
0.1MF. 50V.
LM305A
47PF. 50V.
270Ω
2000MF. 25V.
(2) IN4004
0.47MF. TANT. 25V.
10MF. TANT. 16V.
79M05UC
3 AMP FUSE
14V.
8
0
11
7 CONDUIT
IN4004
(4) IN4004
1000MF. 35V.
(7) DISPLAY LITES

NOTE *1 FERRITE BEAD FERROXCUBE K5-001-00/38

*3 POWER SUPPLY TO BE USED WITH MOTHERBOARD P.C. 80-900.

WARNING ⏚ IS COMMON CENTER TAP AND IS NOT CONNECTED TO CONDUIT GROUND CIRCUITS.

⏚ IS CONDUIT GROUND AND IS NOT CONNECTED TO COMMON CIRCUITS.

⏚ & ⏚ ARE CONNECTED TOGETHER AT X FORMER FRAME WITH SEPERATE LUGS